


### Схема



Стакан	Резьба	
	1000	M5
2000	02	1/4 "
3000	03	3/8 "
4000	04	1/2 "
5000	06	3/4 "
6000	10	1 "